IR VIDEO THEMOMETER

AX-7550

Manual

10-07/9862

INTRODUCTION

Thank you for purchasing the IR VIDEO Thermometer which is capable of non-contact (infrared) temperature measurements with visual camera at the touch of a button. The built-in laser pointer increases target accuracy while the backlight LCD and handy push-buttons combine for convenient, ergonomic operation.

The IR VIDEO Thermometer can be used to measure the surface temperature of the objects that is improper to be measured by traditional (contact) thermometer (such as moving object, the surface with electricity current or the objects which are uneasy to be touched.)

Proper use and care of this meter will provide years of reliable service.


FEATURES:

- 2.2" TFT LCD display
- 640*480 pixels:30 million pixels)
- Micro SD memory card
- Image (JPEG) and video (AVI)
- Humidity and Air Temperature
- Dual laser targeting
- Type-K thermocouple probe
- Adjustable emissivity
- High accuracy
- Fast response time
- Dewpoint temperature and Wet bulb temperature



Distance & Spot Size

As the distance (D) from the object increases, the spot size (S) of the area measured by the unit becomes larger. The relationship between distance and spot size for each unit is listed below. The focal point for each unit is 914mm (36").



Specifications

1. IR temperature measurement

Temperature Range:	-50 to 1600℃ (-58 to 2912℉)	
D: S:	50:1	
Accuracy:	±1%±1.0℃ (1.8℉):	20 to 500℃ (68 to 932℉)
	±1.5%:	500 to 1000℃ (932 to 1832℉)
	±2%	1000 to 1600℃(1832 to 2912℉)
	±3.5℃ (6.3℉)	-50 to 20℃(-58 to 68℉)
Display resolution:	0.1℃ (0.1℉)	1000
	1℃ (1℉)	>1000
Repeatability:	±1.5℃ (2.7℉):	-50 to 20℃ (-58 to 68℉)
	±0.5% or ±0.5℃ (0.9℉)	20 to 1000℃ (68 to 1832℉)
	±1%	1000 to 1600℃(1832 to 2912℉)
Response Time:	150mS	
Spectral Response:	8 ~14um	
Emissivity:	Digitally adjustable form 0.10 to 1.00	

2. Type-k temperature measurement

Temperature Range:	-50 to 1370℃ (-58 to 2498℉)	
Accuracy:	±0.5%±1.5℃ (2.7℉)	0 to 1370℃ (32 to 2498℉)
	±2.5℃ (4.5℉)	-50 to 0℃ (-58 to 32℉)
Display resolution	0.1℃ (0.1℉)	<1000
	1℃ (1℉)	>1000

3. Air temperature and Relative Humidity measurement

Air Temperature Range:	0 to 50℃ (32to 122℉)	
Dewpoint Temperature Range:	0 to 50℃ (32to 122℉)	
Relative Humidity Range:	0 to 100% RH	
Air temperature Accuracy:	±0.5℃ (0.9℉)	10 to 40℃
	±1.0℃ (1.8℉)	others
Dewpoint temperature Accuracy:	±0.5℃ (0.9℉)	10 to 40℃
	±1.0℃ (1.8℉)	others
Relative Humidity Accuracy:	±3%RH	40% to 60%
	±3.5%RH	0%to40%and 60%to 80%
	±5%RH	0%to20%and 80%to 100%

Operating Temperature:	0 to 50℃ (32 to 122℉)
Storage Temperature:	-10 to 60℃ (14 to 140℉)
Relative Humidity:	10 to 90%RH non-condensing
Display:	2.2” 320*240 color LCD with backlight

POWER


Battery:	Rechargeable battery
Battery Life:	About 4 hours continuous use
Battery Charge Time:	About 2 hours with AC adapter or USB connection
Size (H*W*L):	205mm*62mm*155mm
Weight:	410g





Item FRONT PANEL AND BUTTON DESCRIPTION	Description
1.	LCD Display
2.	BUTTONS
3.	Battery Cover
4.	Measurement Trigger
5.	Retractable Lens Cover
6.	Visual camera
7.	Laser
8.	IR sensor
9.	Type-k thermocouple socket

10.	USB computer interface socket
11.	Micro SD memory card
12.	Battery



Item	Description
1	UP or Picture button
2	ESC button
3	Down or VIDEO button
4	Mode button

Menu Overview

Power on or power off

On the power off mode, press and hold ESC button, until the LCD is on, then the unit will power on.

On the power on mode, Press and hold the ESC button, until the LCD is off, then the unit will power off.

1. **Measurement Mode**

The IR VIDEO thermometer has six modes.

On the power on mode, press the ESC button, the unit will display the six modes. You can use UP or DOWN button to select any mode you need.




Symbol	Description	Symbol	Description
	CAM mode		High alarm
	IR mode		High alarm working
	DEWPOINT mode		Low alarm
	Laser		Low alarm working
	Scan		Hold

2. **CAM mode**

Use to measure IR temp, air temp, air humi, dewpoint temperature and wet bulb temperature with camera. It is can display the IR MAX temp., MIN temp., DIF temp., AVG temp.

Press and hold trigger to measure the temperature. This mode can take picture and take video.



2.1. Take picture function



On the CAM mode, press the▲ button to enter picture taking, then press SAVE with ▲ button to save pictures, or press CENCEL with ▼button to cancel.

2.2. Take video function



On the CAM mode, press the ▼button to enter video taking mode, then press START with ▼ button to take videos, or press ESC button to esc.



Press STOP with ▼button to stop the video.

3. IR mode

Use to measure IR temp, air temp, air humi, dewpoint temperature and wet bulb temperature without camera. It is can display the IR MAX temp., MIN temp., DIF temp., AVG temp.



Press and hold trigger to measure the temperature.

4. DEWPOINT mode




measure the IR temp. and dewpoint temp.

Press and hold trigger to measure the temperature.



This is that the IR temperature and dewpoint temperature close to the percentage of

5. Data log



In the DATALOG mode, first set the parameter, like high alarm value, low alarm value, interval time, and the line color, then press the trigger to start logging. The unit will automatically record data , press the ESC buttom to esc the DATALOG mode, then the data will automatically save.

5.1. Set the datalog parameter

Set high alarm value

Press the ENTER button , use the ▲ and ▼ button to adjust the value, then press the ENTER button to confirm.

Set low alarm value

Press the ENTER button , use the ▲ and ▼ button to adjust the value, then press the ENTER button to confirm.


Set interval time

Press the ENTER button , use the ▲ and ▼ button to adjust the value, then press the ENTER button to confirm.

Select the color

Press the ENTER button, use the ▲ and ▼ button to select the color, then press the ENTER button to confirm

6. Gallery



Items	Descriptions
Picture	Display the saved pictures
Video	Play the saved videos
Logs	Display the data log and view


Press the ▲and ▼ button to select the picture, video or Logs. Then press the ENTER button to enter.

In the picture .video or logs, press the ENTER button to view picture, play video or view log. Then press the ENTER button to delete the picture, video or log. Press the ▲ button to confirm to delete, press ▼ button to cancel.



7. SETTINGS





Press the ▲ and ▼ button to select the Items, Then press the ENTER button to enter

Items	Descriptions
Date/Time	Set date and time
Units(C/F)	Select the temperature unit
Language	Select language
Font Color	Select the font color
Cursor	Select cursor or off
Backlight	Backlight brightness adjustment
Auto Power off	Select auto power off time
Screen Timeout	Select screen auto off time
Keypress Alert	Able or disable of Keypress Alert
Memory Status	Display the memory and SD card capacity
Factory Setting	Restore factory settings

7.1. Date/Time




Press the ▲ and ▼ button to select the value, press the ENTER button to set the next value, press ESC button to esc and save the date and time.

7.2. Units(C/F)




Press the ▲ and ▼ button to select the unit, press the ESC button to esc and save.

7.3. Language




Press the ▲ and ▼ button to select the language, press the ESC button to esc and save.

7.4. Font Color




Press the ▲ and ▼ button to select the color, press the ESC button to esc and save.

7.5. Cursor



Press the ▲ and ▼ button to select the cursor (off, cross or circle), press the ESC button to esc and save.

7.6. Backlight



Press the ▲ and ▼ button to select the backlight brightness, press the ESC button to esc and save.

7.7. Auto Power off




Press the ▲ and ▼ button to select the auto power off time or never auto power off, press the ESC button to esc and save.

7.8. Screen Timeout




Press the ▲ and ▼ button to select the screen auto off time or never screen auto off, press the ESC button to esc and save.

7.9. Keypress Alert




Press the ▲ and ▼ button to enable or disable the keypress alert, press the ESC button to esc and save.

7.10. Memory Status



Press the ▲ and ▼ button to select the memory (Device Memory or SD Card). Press the ESC button to esc and save.

NOTE: If SD card inserted, SD card will be selected by default



Format: Select Device Memory or SD card and press the ENTER button to enter format mode, and then press ▲ button to confirm format or press ▼ button to cancel format,.


7.11. Factory Setting




Press the ▲ and ▼ button to select yes or no restore factory settings. Press the ESC button to esc and save.

On any mode, press the ENTER button into the menu.

Measure set






Items	Descriptions
Emissivity set	Set the emissivity
Alarm High	On or off the high alarm and set the value
Alarm Low	On or off the low alarm and set the value
Laser	Able or disable of laser
Auto Mode	Lock to continue measure
Max/Min	Display the max. or min. IR temperature
Average/Dif	Display the average or difference of IR temp.
Ambient TEMP/% RH	Display the air temperature and humidity
Dewpoint/wet bulb	Display the dewpoint and wet bulb temperature
Type k	Enable or disable the type-k input

Emissivity set




ON the first line (ε=0.94),,press the ENTER button to adjust emissivity, Press the ▲ and ▼ button to adjust the value, then press the ENTER button conform. Press the ▲ and ▼ button to select the emissivities of the materials, press the ESC button to esc and save.

Alarm High




Press the ▲ and ▼ button to Enable or Disable the high alarm. If the high alarm is enable, press the ENTER button to enter adjustment, press the ▲ and ▼ button to adjust the value. Press the ENTER button to conform, press the ESC button to esc and save.

Alarm Low




Press the ▲ and ▼ button to Enable or Disable the low alarm. If the low alarm is on, press the ENTER button to adjust, press the ▲ and ▼ button to adjust value. Press the ENTER button to conform, press the ESC button to esc and save.

Laser



Press the ▲ and ▼ button to enable or disable laser, press the ESC button to esc and save.

Auto Mode



Press the ▲ and ▼ button to enable or disable auto mode, press the ESC button to esc and save.

If enable the auto mode, the unit will automatic continue measure, on the status, press the ENTER button, and then press UP button to exit the lock status, press the DOWN button to on or off the laser.



Max/Min



Press the ▲ and ▼ button to on or off display the max. or min. IR temperature ,press the ESC button to esc and save.

Average/Dif



Press the ▲ and ▼ button to on or off display the average or difference of IR temp. , press the ESC button to esc and save.

Ambient TEMP/% RH




Press the ▲ and ▼ button to on or off display the air temperature and humidity, press the ESC button to esc and save.

Dewpoint/wet bulb



Press the ▲ and ▼ button to on or off display the dewpoint and wet bulb temperature, press the ESC button to esc and save.

Type k



Press the ▲ and ▼ button to enable or disable Type k input, and then press the ESC button to esc and save.

NOTE: If insert Type-k probe, Enable will be selected by default. Users can select the Disable, prohibiting LCD display Type-k temperature.

N

NOTES:

- **How it Works**

  Infrared thermometers measure the surface temperature of an object. The unit's optics sense emitted, reflected, and transmitted energy, which is collected and focused onto a detector. The unit's electronics translate the information into a temperature reading, which is display on the unit. In units with a laser, the laser is used for aiming purposes only.

- **Field of View**

  Make sure that the target is larger than the unit's spot size. The smaller the target is, the closer you should be to it. When accuracy is critical, make sure the target is at least twice as large as the spot size.

- **Distance & Spot Size**

  As the distance (D) from the object increases, the spot size (S) of the area measured by the unit becomes larger. See: **Fig: 1**.

- **Locating a hot Spot**

  To find a hot spot aim the thermometer outside the area of interest, then scan across with an up and down motion until you locate hot spot.

- **Reminders**

  1. Do not use the unit to measure shiny or polished metal surfaces (stainless steel, aluminum, etc.).See **Emissivity**
  2. The unit cannot be measured through transparent surfaces such as glass. It will measure the surface temperature of the glass instead.
  3. Steam, dust, smoke, etc., Can prevent accurate measurement by obstructing the unit's optics.

- **Emissivity**

  Emissivity is a term used to describe the energy-emitting characteristics of materials.

  Most (90% of typical applications) organic materials and painted or oxidized surfaces have an emissivity of 0.95 (pre-set in the unit). Inaccurate readings will result from measuring shiny or polished metal surfaces. To compensate, cover the surface to be measured with masking tape or flat black paint. Allow time for the tape to reach the same temperature as the material underneath it. Measure the temperature of the tape or painted surface.

Emissivity Values

Substance	Thermal emissivity	Substance	Thermal emissivity
Asphalt	0.90 to 0.98	Cloth (black)	0.98
Concrete	0.94	Human skin	0.98
Cement	0.96	Lather	0.75 to 0.80
Sand	0.90	Charcoal (powder)	0.96
Earth	0.92 to 0.96	Lacquer	0.80 to 0.95
Water	0.92 to 0.96	Lacquer (matt)	0.97
Ice	0.96 to 0.98	Rubber (black)	0.94

Snow	0.83	Plastic	0.85 to 0.95
Glass	0.90 to 0.95	Timber	0.90
Ceramic	0.90 to 0.94	Paper	0.70 to 0.94
Marble	0.94	Chromium oxides	0.81
Plaster	0.80 to 0.90	Copper oxides	0.78
Mortar	0.89 to 0.91	Iron oxides	0.78 to 0.82
Brick	0.93 to 0.96	Textiles	0.90

MAINTENANCE

- Repairs or service are not covered in this manual and should only be carried out by qualified trained technician.
- Periodically, wipe the body with a dry cloth. Do not use abrasives or solvents on this instrument.
- For service, use only manufacturer's specified parts.

